Stepper Motor Theory

Motors convert electrical energy into mechanical energy. A stepper motor converts electrical pulses into specific rotational movements. The movement created by each pulse is precise and repeatable, which is why stepper motors are so effective for positioning applications.

Permanent Magnet stepper motors incorporate a permanent magnet rotor, coil windings and magnetically conductive stators. Energizing a coil winding creates an electromagnetic field with a north and south pole as shown in figure 1. The stator carries the magnetic field which causes the rotor to align itself with the magnetic field. The magnetic field can be altered by sequentially energizing or "stepping" the stator coils which generates rotary motion.

Figure 1. Magnetic field created by energizing a coil winding

Figure 2 illustrates a typical step sequence for a two phase motor. In Step 1 phase A of a two phase stator is energized. This magnetically locks the rotor in the position shown, since unlike poles attract. When phase A is turned off and phase B is turned on, the rotor rotates 90° clockwise. In Step 3, phase B is turned off and phase A is turned on but with the polarity reversed from Step 1. This causes another 90° rotation. In Step 4, phase A is turned off and phase B is turned on, with polarity reversed from Step 2. Repeating this sequence causes the rotor to rotate clockwise in 90° steps.


Figure 2. "One phase on" stepping sequence for two phase motor.

The stepping sequence illustrated in figure 2 is called "one phase on" stepping. A more common method of stepping is "two phase on" where both phases of the motor are always energized. However, only the polarity of one phase is switched at a time, as shown in figure 3. With two phase on stepping the rotor aligns itself between the "average" north and "average" south magnetic poles. Since both phases are always on, this method gives 41.4% more torque than "one phase on" stepping, but with twice the power input.


Figure 3. "Two phase on" stepping sequence for two phase motor.

Half Stepping

The motor can also be "half stepped" by inserting an off state between transitioning phases. This cuts a stepper's full step angle in half. For example, a 90° stepping motor would move 45° on each half step, figure 4. However, half stepping typically results in a 15% - 30% loss of torque depending on step rate when compared to the two phase on stepping sequence. Since one of the windings is not energized during each alternating half step there is less electromagnetic force exerted on the rotor resulting in a net loss of torque.

Figure 4. Half-stepping – 90° step angle is reduced to 45° with half-stepping.

Bipolar Winding

The two phase stepping sequence described utilizes a "bipolar coil winding." Each phase consists of a single winding.   By reversing the current in the windings, electromagnetic polarity is reversed. The output stage of a typical two phase bipolar drive is further illustrated in the electrical schematic diagram and stepping sequence in figure 5. As illustrated, switching simply reverses the current flow through the winding thereby changing the polarity of that phase.

CW Rotation ↓   CCW Rotation ↑

Bipolar Step	Q2-Q3	Q1-Q4	Q6-Q7	Q5-Q8
1	ON	OFF	ON	OFF
2	OFF	ON	ON	OFF
3	OFF	ON	OFF	ON
4	ON	OFF	OFF	ON
1	ON	OFF	ON	OFF

Figure 5. Wiring diagram and step sequence for bipolar motor.

Unipolar Winding

Another common winding is the unipolar winding. This consists of two windings on a pole connected in such a way that when one winding is energized a magnetic north pole is created, when the other winding is energized a south pole is created. This is referred to as a unipolar winding because the electrical polarity, i.e. current flow, from the drive to the coils is never reversed. The stepping sequence is illustrated in figure 6. This design allows for a simpler electronic drive. However, there is approximately 30% less torque available compared to a bipolar winding. Torque is lower because the energized coil only utilizes half as much copper as compared to a bipolar coil.

CW Rotation ↓   CCW Rotation ↑

| Unipolar Step	Q1	Q2	Q3	Q4
1	ON	OFF	ON	OFF
2	OFF	ON	ON	OFF
3	OFF	ON	OFF	ON
4	ON	OFF	OFF	ON
1	ON	OFF	ON	OFF

Figure 6. Wiring diagram and step sequence for unipolar motor.

Other Step Angles

In order to obtain smaller step angles, more poles are required on both the rotor and stator. The same number of pole pairs are required on the rotor as on one stator. A rotor from a 7.5° motor has 12 pole pairs and each pole plate has 12 teeth. There are two pole plates per coil and two coils per motor; hence 48 poles in a 7.5° per step motor. Figure 7 illustrates the 4 pole plates of a 7.5° motor in a cut away view. Of course, multiple steps can be combined to provide larger movements. For example, six steps of a 7.5° stepper motor would deliver a 45° movement.

Figure 7. Partial cut away showing pole plates of a 7.5° step angle motor.

Accuracy

The accuracy for can-stack style steppers is 6 - 7% per step, non-cumulative. A 7.5° stepper will be within 0.5° of theoretical position for every step, regardless of how many steps are taken. The incremental errors are non-cumulative because the mechanical design of the motor dictates a 360° movement for each full revolution. The physical position of the pole plates and magnetic pattern of the rotor result in a repeatable pattern through every 360° rotation (under no load conditions).

Resonance

Stepper motors have a natural resonant frequency as a result of the motor being a spring-mass system. When the step rate equals the motor's natural frequency, there may be an audible change in noise made by the motor, as well as an increase in vibration. The resonant point will vary with the application and load, but typically occurs somewhere between 70 and 120 steps per second. In severe cases the motor may lose steps at the resonant frequency. Changing the step rate is the simplest means of avoiding many problems related to resonance in a system. Also, half stepping or micro stepping usually reduces resonance problems. When accelerating to speed, the resonance zone should be passed through as quickly as possible.

Torque

The torque produced by a specific rotary stepper motor is a function of:
- **The step rate**
- **The current through the windings**
- **The type of drive used**

(The force generated by a linear motor is also dependent upon these factors.)

Torque is the sum of the friction torque (T_f) and inertial torque (T_i).

$$T = T_f + T_i$$

The frictional torque (ounce-inches or gram-cm) is the force (F), in ounces or grams, required to move a load multiplied by the length, in inches or cm, of the lever arm used to drive the load (r) as shown in figure 8.

$$T_f = F \cdot r$$

Figure 8. Frictional torque is the force (F) required to move a load multiplied by the length of the lever arm (r).

The inertial torque (T_i) is the torque required to accelerate the load (gram-cm^2).

$$T_i = I(\omega/t)\pi\,\theta\,K$$

Where
I	=	the inertial load in g-cm^2
ω	=	step rate in steps/second
t	=	time in seconds
θ	=	the step angle in degrees
K	=	a constant 97.73

It should be noted that as the step rate of a motor is increased, the back electromotive force (EMF) (i.e. the generated voltage) of the motor also increases. This restricts current flow and results in a decrease in useable output torque.

Linear Actuators

The rotary motion of a stepper motor can be converted into linear motion by several mechanical means. These include rack & pinion, belt and pulleys and other mechanical linkages. All of these options require various external mechanical components. The most effective way to accomplish this conversion is within the motor itself.

The linear actuator was first introduced in 1968. Figure 9 shows some typical linear actuators.


Figure 9. HSI Linear Actuators Series 20000, left to right, (3/4" Ø), captive shaft, Series 26000 (1" Ø) non-captive, and Series 36000 (1.4" Ø) captive.

Conversion of rotary to linear motion inside a linear actuator is accomplished through a threaded nut and leadscrew. The inside of the rotor is threaded and the shaft is replaced by a lead screw. In order to generate linear motion the lead screw must be prevented from rotating. As the rotor turns the internal threads engage the lead screw resulting in linear motion. Changing the direction of rotation reverses the direction of linear motion. The basic construction of a linear actuator is illustrated in figure 10.

Figure 10. Linear actuator cut away showing threaded rotor to leadscrew interface.

The linear travel per step of the motor is determined by the motor's rotary step angle and the thread pitch of the rotor nut and leadscrew combination. Coarse thread pitches give larger travel per step than fine pitch screws. However, for a given step rate, fine pitch screws deliver greater thrust. Fine pitch screws usually can not be manually "backdriven" or translated when the motor is unenergized, whereas many coarse screws can. A small amount of clearance must exist between the rotor and screw threads to provide freedom of movement for efficient operation. This results in .001" to .003" of axial play (also called back-lash). If extreme positioning accuracy is required, backlash can be compensated for by always approaching the final position from the same direction.

Accomplishing the conversion of rotary to linear motion inside the rotor greatly simplifies the process of delivering linear motion for many applications. Because the linear actuator is self contained, the requirements for external compo-nents such as belts and pulleys are greatly reduced or eliminated. Fewer compo-nents make the design process easier, reduce overall system cost and size and improve product reliability.

Selecting The Proper Motor

In order to select the proper motor several factors must be considered. Is linear or rotary motion required? Following is a list of some of the basic requirements to consider when choosing a motor. This will help determine if a linear actuator or rotary motor should be used.

Rotary Motor	**Linear Actuator**
How much torque is required?	How much force is required?
What is the duty cycle?	What is the duty cycle?
What is desired step angle?	What is desired step increment?
What is the step rate or RPM?	What is the step rate or speed of travel?
Bipolar or unipolar coils?	Bipolar or unipolar coils?
Coil Voltage?	Coil Voltage?
Detent or holding torque requirements?	Must the screw hold position with power
Are there size restrictions?	off or must it be "backdrivable"with
What is anticipated life requirement?	power off?
Temperature of operating environment?	Are there size restrictions?
Sleeve or ball bearings?	What is anticipated life requirement?
Radial and axial load?	Temperature of operating environment?
	Captive or non-captive shaft?

AC Synchronous Motors

Stepping motors can also be run on AC (Alternating Current). However, one phase must be energized through a properly selected capacitor. In this case the motor is limited to only one synchronous speed. For instance, if 60 hertz is being supplied, there are 120 reversals or alterations of the power source. The phase being energized by a capacitor is also producing the same number of alterations at an offset time sequence. The motor is really being energized at the equivalent of 240 steps per second. For a 15° rotary motor, 24 steps are required to make one revolution (24 SPR). This becomes a 600 RPM synchronous motor.

$$\frac{\textbf{240 SPS x 60 seconds}}{\textbf{24 SPR}} = \textbf{600 RPM}$$

In the case of a linear actuator the linear speed produced is dependent on the resolution per step of the motor. For example if 60 hertz is supplied to a .001"/ step motor the resulting speed is .240" per second (240 steps per second times .001"/step). Many of HSI's stepping motors are available as 300 or 600 RPM AC synchronous motors.

Drives

Stepper motors require some external electrical components in order to run. These components typically include a power supply, logic sequencer, switching components and a clock pulse source to determine the step rate. Many commercially available drives have integrated these components into a complete package. Some basic drive units have only the final power stage without the controller electronics to generate the proper step sequencing.

Bipolar Drive

This is a very popular drive for a two phase bipolar motor having four leads. In a complete driver/controller the electronics alternately reverse the current in each phase. The stepping sequence is shown in figure 5.

Unipolar Drive

This drive requires a motor with a center-tap at each phase (6 leads). Instead of reversing the current in each phase, the drive only has to switch current from one coil to the other in each phase (figure 6). The windings are such that this switching reverses the magnetic fields within the motor. This option makes for a simpler drive but only half of the copper winding is used at any one time. This results in approximately 30% less available torque in a rotary motor or force in a linear actuator as compared to an equivalent bipolar motor.

L/R Drives

This type of drive is also referred to as a constant voltage drive. Many of these drives can be configured to run bipolar or unipolar stepper motors. L/R stands for the electrical relationship of inductance (L) to resistance (R). Motor coil impedance vs. step rate is determined by these parameters. The L/R drive should "match" the power supply output voltage to the motor coil voltage rating for continuous duty operation. Most published motor performance curves are based on full rated voltage applied at the motor leads. Power supply output voltage level must be set high enough to account for electrical drops within the drive circuitry for optimum continuous operation.

Performance levels of most steppers can be improved by increasing the applied voltage for shortened duty cycles. This is typically referred to as "over-driving" the motor. When over-driving a motor, the operating cycle must have sufficient periodic off time (no power applied) to prevent the motor temperature rise from exceeding the published specification.

Chopper Drives

A chopper drive allows a stepper motor to maintain greater torque or force at higher speeds than with an L/R drive. The chopper drive is a constant current drive and is almost always the bipolar type. The chopper gets its name from the technique of rapidly turning the output power on and off (chopping) to control motor current. For this setup, low impedance motor coils and the maximum voltage power supply that can be used with the drive will deliver the best performance. As a general rule, to achieve optimum performance, the recommended ratio between power supply and rated motor voltage is eight to one. An eight to one ratio was used for the performance curves in this catalog.

Microstepping Drives

Many bipolar drives offer a feature called microstepping. Microstepping electronically divides a full step into smaller steps. For instance, if one step of a linear actuator is 0.001 inch, this can be driven to have 10 microsteps per step. In this case, one microstep would normally be 0.0001 inch. Microstepping effectively reduces the step increment of a motor. However, the accuracy of each microstep has a larger percentage of error as compared to the accuracy of a full step. As with full steps, the incremental errors of microsteps are non-cumulative.

Fatigue / Life

With proper application, HSI's linear actuators deliver up to 20 million cycles and HSI's rotary motors provide up to 25,000 hours of service. Ultimately motor fatigue and resultant life are determined by each customer's unique application.

The following definitions are important for understanding motor life and fatigue.

Continuous Duty: Running a motor at its rated voltage.

25% Duty Cycle: Running a motor at double its rated voltage on an L/R drive. The motor is "on" approximately 25% of the time. The motor generates about 60% more output than at rated voltage. Note, duty cycle is not related to the load placed on the motor.

Life: A linear actuator's life is the number of cycles that the motor is able to move at a prescribed load and maintain step accuracy. Rotary motor life is the number of hours of operation.

One Cycle: A linear actuator's cycle consists of extending and retracting back to the original position.

There are some general guidelines which can be used to choose a proper motor and ensure maximum life. Ultimately, to determine a stepper's performance in a given system it is best to perform testing of the final assembly in "field conditions" or in a setting which closely approximates those conditions.

Since a stepper motor has no brushes to wear out, its life usually far exceeds that of other mechanical components in a system. If a stepper does fail there are certain components which are likely to be involved. Bearings and lead screw/nut interface (in linear actuators) are typically the first components to experience fatigue. Required torque or thrust and operating environment are the factors which affect these motor components.

If the motor is run at or near its rated torque or thrust, life will be affected. HSI testing has shown that motor life increases exponentially with reduced operating loads. In general, motors should be designed in a device to run at 40% to 60% of their maximum load capability. Environmental factors such as high humidity, exposure to harsh chemicals, excessive dirt/debris and heat will all affect motor life. Mechanical factors in the assembly such as side loading of the shaft for linear actuators or an unbalanced load in rotary applications will also adversely affect life.

If the motor is used at a reduced duty cycle and excessive voltage is applied to the motor, the "on" time must be such that the maximum temperature rise for the motor is not exceeded. If the motor does not have enough "off" time, too much heat will be generated causing the windings to overheat and eventually fail.

Properly designing a system which minimizes these factors will ensure maximum motor life. The first step for maximizing life is choosing a motor which has a safety factor of two or greater. The second step is ensuring the system is mechanically sound by minimizing side loads, unbalanced loads and impact loads. The system should also dissipate heat. Air flow around the motor or mounting which provides some heat sinking are typical means for heat dissipation. If harsh chemicals are present in the system the motor and all other components must be protected. Finally, testing the motor and assembly in "field conditions" will ensure fitness for the application.

If these simple guidelines are followed HSI linear actuators provide reliable operation in a wide range of applications. If you need assistance with your design, HSI's applications engineers are available to help you get maximum life and performance from our motors.

Summary

Stepper motors have been used in a wide array of applications for many years. With trends towards miniaturization, computer control and cost reduction, "can-stack" style steppers are being used in an ever increasing range of applications. In particular the use of linear actuators has rapidly expanded in recent years. These precise, reliable motors can be found in many applications including blood analyzers and other medical instrumentation, automated stage lighting, imaging equipment, HVAC equipment, valve control, printing equipment, X-Y tables, integrated chip manufacturing, inspection and test equipment. This attractive technical solution eliminates the use of numerous components and the associated costs related to assembly, purchasing, inventory, etc. The applications for these motors are only limited by the designer's imagination.

Terminology

Detent or residual torque: The torque required to rotate the motor's output shaft with no current applied to the windings.

Drives: A term depicting the external electrical components to run a Stepper Motor System. This will include power supplies, logic sequencers, switching components and usually a variable frequency pulse source to determine the step rate.

Dynamic torque: The torque generated by the motor at a given step rate. Dynamic torque can be represented by PULL IN torque or PULL OUT torque.

Holding torque: The torque required to rotate the motor's output shaft while the windings are energized with a steady state D.C. current.

Inertia: The measure of a body's resistance to acceleration or deceleration. Typically used in reference to the inertia of the load to be moved by a motor or the inertia of a motor's rotor.

Linear step increment: The linear travel movement generated by the leadscrew with each single step of the rotor.

Maximum temperature rise: Determined by the resistance rise method, motor unmounted in free air and energized with a steady state D.C. current.

Pull in torque: The load a motor can move without missing steps when started at a constant pulse rate.

Pull out torque: The load a motor can move when at operating speed. This is normally substantially greater than the Pull in torque.

Pulse rate: The number of pulses per second (pps) applied to the windings of the motor. The pulse rate is equivalent to the motor step rate.

Pulses per second (PPS): The number of steps that the motor takes in one second (sometimes called "steps per second"). This is determined by the frequency of pulses produced by the motor drive.

Ramping: A drive technique to accelerate a given load from a low step rate, to a given maximum step rate and then to decelerate to the initial step rate without the loss of steps.

Single step response: The time required for the motor to make one complete step.

Step: The angular rotation produced by the rotor each time the motor receives a pulse. For linear actuators a step translates to a specific linear distance.

Step angle: The rotation of the rotor caused by each step, measured in degrees.

Steps per revolution: The total number of steps required for the rotor to rotate 360°.

Torque to inertia ratio: Holding torque divided by rotor inertia.